



Thurgood Marshall Academy PCS - Lead in Water Test Results



FY20 Filter Test

Less than 5 ppb - Devices Requiring No Remediation												
Charter Campus Name	Water Source ID	Device Type	Floor	Device Location	Location Identifier		Water Filter ID	Date Analyzed	Draw A Sample ID	FT Final Results - Draw A (ppb)	Draw B Sample ID	FT Final Results - Draw B (ppb)
					High/Low	Left/Mid/Right						
Thurgood Marshall Academy PCS	WS-119-001	Food Prep Sink	Ground	In kitchen		Left	WF-092019-119001-03	12/31/2019	FT-FY20-092019-119001-A	1.8	FT-FY20-092019-119001-B	<1
Thurgood Marshall Academy PCS	WS-119-003	Cooler	Ground	In hallway adjacent to lunch room			WF-092019-119003-03	12/31/2019	FT-FY20-092019-119003-A	<1	FT-FY20-092019-119003-B	<1
Thurgood Marshall Academy PCS	WS-119-004	Health Suite	Ground	In health suite			WF-092019-119004-03	12/31/2019	FT-FY20-092019-119004-A	<1	FT-FY20-092019-119004-B	<1
Thurgood Marshall Academy PCS	WS-119-005	Cooler	Ground	In hallway adjacent to music room (012)			WF-092019-119005-03	12/31/2019	FT-FY20-092019-119005-A	<1	FT-FY20-092019-119005-B	<1
Thurgood Marshall Academy PCS	WS-119-006	Cooler	1	In hallway adjacent to science room (112)			WF-092019-119006-03	12/31/2019	FT-FY20-092019-119006-A	<1	FT-FY20-092019-119006-B	<1
Thurgood Marshall Academy PCS	WS-119-007	Cooler	2	In hallway adjacent to library (213)			WF-092019-119007-03	12/31/2019	FT-FY20-092019-119007-A	<1	FT-FY20-092019-119007-B	<1
Thurgood Marshall Academy PCS	WS-119-009	Cooler	2	In hallway adjacent to room 206			WF-092019-119009-03	12/31/2019	FT-FY20-092019-119009-A	<1	FT-FY20-092019-119009-B	<1
Thurgood Marshall Academy PCS	WS-119-010	Break Room	2	In teachers' lounge			WF-092019-119010-03	12/31/2019	FT-FY20-092019-119010-A	<1	FT-FY20-092019-119010-B	<1
Thurgood Marshall Academy PCS	WS-119-011	Food Prep Sink	Ground	In kitchen			WF-092019-119011-03	12/31/2019	FT-FY20-092019-119011-A	3	FT-FY20-092019-119011-B	<1
Thurgood Marshall Academy PCS	WS-119-012	Health Suite	Ground	In health suite			WF-092019-119012-03	12/31/2019	FT-FY20-092019-119012-A	<1	FT-FY20-092019-119012-B	<1
Thurgood Marshall Academy PCS	WS-119-013	Break Room	2	In teachers lounge (coffee maker)			WF-092019-119013-03	12/31/2019	FT-FY20-092019-119013-A	<1	FT-FY20-092019-119013-B	<1

Greater than 5 ppb - Devices Requiring Remediation												
Charter Campus Name	Water Source ID	Device Type	Floor	Device Location	Location Identifier		Water Filter ID	Date Analyzed	Draw A Sample ID	FT Final Results - Draw A (ppb)	Draw B Sample ID	FT Final Results - Draw B (ppb)
					High/Low	Left/Mid/Right						
Thurgood Marshall Academy PCS	WS-119-002	Food Prep Sink	Ground	In kitchen		Right	WF-092019-119002-03	12/31/2019	FT-FY20-092019-119002-A	5.3	FT-FY20-092019-119002-B	<1

FY20 Filter Test (After Plumbing Check)

Less than 5 ppb - Devices Requiring No Remediation												
Charter Campus Name	Water Source ID	Device Type	Floor	Device Location	Location Identifier		Water Filter ID	Date Analyzed	Draw A Sample ID	FT Final Results - Draw A (ppb)	Draw B Sample ID	FT Final Results - Draw B (ppb)
					High/Low	Left/Mid/Right						
Thurgood Marshall Academy PCS	WS-119-002	Food Prep Sink	Ground	In kitchen		Right	WF-012020-119002-04	1/14/2020	FT-FY20-012020-119002-A	2.5	FT-FY20-012020-119002-B	<1